

## RESOLUTION NO. 2023-20

### A RESOLUTION DECLARING THE BUILDING OR STRUCTURE, OR THE PREMISES LOCATED AT 308 NORTH WHITE SANDS BOULEVARD ALAMOGORDO, OTERO COUNTY, NEW MEXICO, TO BE RUINED, DAMAGED, AND DILAPIDATED TO BE A MENACE TO THE PUBLIC COMFORT, HEALTH, PEACE, OR SAFETY, AND ORDERING ITS ABATEMENT

**WHEREAS**, the governing body of the City of Alamogordo, New Mexico, finds that there is located within the City a certain building, structure, or premises at 308 North White Sands Boulevard, as more particularly described on the attached Exhibit 1 (the "Property"); and,

**WHEREAS**, the governing body does further find that the Code Enforcement Manager has investigated the condition of the Property and has found the same to be so ruined, damaged, and dilapidated, or covered with ruins, rubbish, wreckage, or debris, that it constitutes a menace to the public comfort, health, peace or safety so as to warrant abatement.

#### **NOW, THEREFORE, BE IT RESOLVED BY THE CITY COMMISSION:**

Section 1. That the findings of said Code Enforcement Manager, in regard to the Property, attached hereto as Exhibit 2, are hereby approved and adopted, and that the Property is found to be ruined, damaged, and dilapidated, so as to constitute a menace to the public comfort, health, peace or safety pursuant to Section 3-18-5, NMSA, 1978.

Section 2. That Mr. Christopher Douglass, the record owner of the Property, is hereby ordered to commence removal of the building or structure from the Property within ten (10) days after service of a copy of this Resolution, or within said ten (10) day period, file written objection to findings herein with the City Clerk of the City of Alamogordo, asking for a hearing before the City Commission.


Section 3. That if there is a failure of compliance with the provision of Section 2 herein, the City of Alamogordo shall proceed to remove said building or structure from the Property and abate said unsafe condition, at the cost and expense of said record, with said cost and expense constituting a lien against the building or structure so removed, and against the Property, as allowed by law.

Section 4. SEVERABILITY CLAUSE. If any section, paragraph, sentence, clause, word, or phrase of this resolution is for any reason held to be invalid or unenforceable by any court of competent jurisdiction, such decision shall not affect the validity of the remaining provisions of this resolution. The Commission hereby declares that it would have passed this resolution and each section, paragraph, sentence, clause, word, or phrase thereof, irrespective of any provisions being declared unconstitutional or otherwise invalid.

**PASSED, APPROVED AND ADOPTED**, this 12<sup>th</sup> day of September 2023.

CITY OF ALAMOGORDO, NEW MEXICO  
a New Mexico municipal corporation




By:   
Susan L. Payne, Mayor

ATTEST:

  
Rachel Hughs, City Clerk

APPROVED AS TO FORM:

  
Ashley Smith, City Attorney

- [Account Search](#)
- [My Reports](#)
- [Help](#)
- [Logout Public](#)

Exhibit "1"

**Account: R010833**

Location

Account Number R010833  
 Situs Address 308 N WHITE SANDS BLVD  
 Previous Parcel ID 01-01156  
 Parcel Sequence  
 Neighborhood C31 - Commercial White Sands  
 Tax Area 01\_NR  
 Parcel Number 01N4055094095407  
 Legal Summary Subd: ALAMO BLOCKS Lot: 5. 6 Block: 8  
 Appraiser Ricardo Heredia

Owner Information

Owner Name DOUGLASS, CHRISTOPHER  
 Owner Address 2405 PRINCETON  
 ALAMOGORDO, NM 88310

Assessment History

Actual (2023) \$47,527  
 Primary Taxable \$15,842  
 Tax Area: 01\_NR Mill Levy: 33.247000  

| Type                        | Actual   | Assessed Acres | SQFT     |
|-----------------------------|----------|----------------|----------|
| Non-Residential Land        | \$36,000 | \$12,000       | 0.138    |
| Non-Residential Improvement | \$11,527 | \$3,842        | 4452.000 |

Transfers

| Sale Date | Sale Price | Doc Description               |
|-----------|------------|-------------------------------|
|           |            | <a href="#">Deed</a>          |
|           |            | <a href="#">Warranty Deed</a> |

Tax History

| Tax Year | Taxes    |
|----------|----------|
| *2023    | \$526.68 |
| 2022     | \$524.16 |

\* Estimated

Images

- [Map](#)
- [Photo](#)
- [Sketch](#)
- [GIS](#)

Focusing On: 308 N WHITE SANDS BLVD ALAMOGORDO 88310






Exhibit "2"

Case #: 202300926

Case Date: 04/20/23

Address Number: 308

Street Name: N. White Sands Blvd

Complainant Phone: (575)439-4375

Description: Dilapidated Structure

Complainant Address: 2010 Oregon Ave.

Complainant Name: Sides

Reinspection: 05/12/2023

**Compliance Inspection :**

Property Owners : Christopher Douglass

Court case number:

DOB: 05/27/1966

ID #:

Court Date:

Status: Mailed IPMC Letter

Assigned To: JOSH SIDES

**Property**

| Parcel #         | Address                | Legal Description                        | Owner Name               | Owner Phone | Zoning |
|------------------|------------------------|------------------------------------------|--------------------------|-------------|--------|
| 01N4055094095407 | 308 N WHITE SANDS BLVD | Subd: ALAMO BLOCKS<br>Lot: 5, 6 Block: 8 | DOUGLASS,<br>CHRISTOPHER |             |        |

**Activities**

| Date | Activity Type | Description | Employee | Status |
|------|---------------|-------------|----------|--------|
|------|---------------|-------------|----------|--------|

|            |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |            |                |
|------------|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|----------------|
| 04/20/2023 | Inspection    | <p>On 04/20/2023, I, Code Enforcement Manager Josh Sides, was informed of a dilapidated structure at 308 N. White Sands Blvd., Alamogordo, Otero County, New Mexico.</p> <p>I met with Code Enforcement Officer Otero at the property to discuss it. Officer Otero took me to the east side of the property in the alleyway. He informed me that the large cracks in the northeast corner had grown exponentially in the past few weeks. The cracks ran from the ground to the top of the exterior wall and were approximately two inches wide in the most severe areas. There were also cinder blocks missing from the wall in some places. I observed there to be numerous amounts of graffiti on the back side of the building as well. The front side of the building had cracks in the exterior walls and graffiti on them. The south side of the building's exterior wall had numerous cracks and an abundance of graffiti. The fascia on the building was pulled off in some areas and rusted. The electrical box had been pulled off the building and was hanging from the wiring inside the conduit. There was paint on some areas of the building, but in others, there was no paint or protective coating on the cinder block. I photographed the condition of the property.</p> <p>I requested help from Paul Bennett, Facility Maintenance Manager for the City of Alamogordo, to look at the property as he holds his General Contractors License. Paul stated that the cinder block structure is settled on the northeast and southwest corners and is separating/falling away, causing both corners of the building to be unstable. Paul stated the cracking on the northeast and southwest corners is causing a potential collapse hazard.</p> <p>On 04/24/2023, I met with the City of Alamogordo Attorney's Office, the City of Alamogordo Engineering Department, and the Public Works Director for the City of Alamogordo to discuss this property. I learned that in 2022, an Administrative Search Warrant was executed on the property. However, there was no documentation as to the condition of the property. It was determined that declaring the property as unsafe pursuant to the City of Alamogordo Code of Ordinances 8-03-170 will start from the beginning.</p> <p>On 04/24/2023, I drafted an International Property Maintenance Code Violation Letter to give to the Property owner, which through research of the Otero County Assessors Office, was identified as Mr. Christopher Douglass.</p> <p>I attempted to contact Mr. Douglas at his listed address on 04/25/2023 and again on 04/26/2023 but was unsuccessful. The letter was mailed certified to Mr. Douglas on 04/26/2023.</p> <p>The photographs I took of the property, a copy of the letter mailed, and copies of the certified letter envelope were uploaded to iWorQ.</p> | JOSH SIDES | Non-Compliance |
| 05/22/2023 | Re-Inspection | <p>On 05/22/2023, I, Code Enforcement Manager Josh Sides, applied for and was granted an Administrative Search Warrant by 12th Judicial District Court Judge Bryant for the property at 308 N. White Sands Blvd.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | JOSH SIDES | Closed         |
| 05/23/2023 | Re-Inspection | <p>On 05/23/2023, I, Code Enforcement Manager Josh Sides, executed an Administrative Search Warrant on the property at 308 N. White Sands Blvd., Alamogordo, Otero County, New Mexico, at approximately 2:00 PM MST.</p> <p>Assisting me with the execution of the search warrant were:<br/> Paul Bennett- Facility Maintenance Manager (COA)<br/> Jeremy Otero- Code Enforcement Officer (COA)<br/> Rocky Chavez- Code Enforcement Officer (COA)<br/> Sgt. Brown (APD)<br/> Ofc. Puente (APD)<br/> Ofc. Buffington (APD)<br/> Nancy Beshaler- Public Works Director (COA).</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | JOSH SIDES | Closed         |
|            |               | <p>The front door of the property was locked with a padlock that was cut to allow us entry into the property's interior. Upon entry, APD officers made sure there were no people inside or obvious hazards to the rest</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |            |                |

of the employees. Once APD officers declared the building safe, the rest of the employees made entry. I began to take photographs of the state of the interior of the building along with Code Officers Chavez and Otero, while Paul Bennett began to inspect the building., I observed there to be numerous hazards and violations of the International Property Maintenance Code associated with the building. The violations of the International Property Maintenance Code were 305.1.1 Unsafe Conditions, 304.7 Roofs and Drainage, 305.4 Stairs and Walking Surfaces, and 305.1 General. All the pictures taken were uploaded to iWorQ. I posted the Search Warrant on the window of the property and mailed a copy of the Search Warrant to the property owner.

## Violations

| Date       | Violation                                                  | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Notes                                                                                                                                                      | Status |
|------------|------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 04/20/2023 | *8-03-080- International Property Maintenance Code Adopted | (a)With the exceptions and amendments set forth below, the city hereby adopts by reference the conditions, provisions, limitations and terms of the International Property Maintenance Code, 2006 Edition, published by the International Code Council, including any amendments thereto which are adopted by the state as of the date of or subsequent to the date of this section.(b)Except as specified within section 8-03-150 and 8-03-160 of this section appeals from orders, decisions or determinations of the code official relative to the application and interpretation of this code shall be submitted to the International Code Council for official interpretation. The official interpretation shall constitute the final decision on any appeal. | Several violations of the International Property Maintenance Code.                                                                                         | *Open  |
| 04/20/2023 | IPMC 301.3 Vacant Structures and Land.                     | All vacant structures and premises thereof or vacant land shall be maintained in a clean, safe, secure and sanitary condition as provided herein so as not to cause a blighting problem or adversely affect the public health or safety                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Building has not been maintained in a clean, safe, secure, and sanitary condition. Several cracks to walls and settling of the building.                   | *Open  |
| 04/20/2023 | IPMC 302.9- Defacement of Property                         | No person shall willfully or wantonly damage, mutilate or deface any exterior surface of any structure or building on any private or public property by placing thereon any marking, carving or graffiti. It shall be the responsibility of the owner to restore said surface to an approved state of maintenance and repair.                                                                                                                                                                                                                                                                                                                                                                                                                                      | Several areas of graffiti on the building on all sides.                                                                                                    | *Open  |
| 04/20/2023 | IPMC 304.1 - General                                       | The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | The structure's exterior is not in good repair, structurally sound, or sanitary and poses a threat to public health, safety, and welfare.                  | *Open  |
| 04/20/2023 | IPMC 304.13 Window, skylight and door frames               | Every window, skylight, door and frame shall be kept in sound condition, good repair and weather tight.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | Windows, doors, and frames are not in sound condition, good repair, or weather tight.                                                                      | *Open  |
| 04/20/2023 | IPMC 304.2 - Protective Treatment                          | Exterior surfaces, including but not limited to, doors, door and window frames, cornices, porches, trim, balconies, decks and fences, shall be maintained in good condition. Exterior wood surfaces, other than decay-resistant woods, shall be protected from the elements and decay by painting or other protective covering or treatment. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted. Siding and masonry joints, as well as those                                                                                                                                                                                                                                                                                            | The exterior walls of the structure to include doors, window frames, and trim are not in good condition and are not protected from the elements with paint | *Open  |

|            |                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                                       |       |
|------------|-----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|-------|
|            |                                   | between the building envelope and the perimeter of windows, doors and skylights, shall be maintained weather resistant and water tight. Metal surfaces subject to rust or corrosion shall be coated to inhibit such rust and corrosion, and surfaces with rust or corrosion shall be stabilized and coated to inhibit future rust and corrosion. Oxidation stains shall be removed from exterior surfaces. Surfaces designed for stabilization by oxidation are exempt from this requirement.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | or other protective covering. Masonry joints are failing in some areas.                                                               |       |
| 04/20/2023 | IPMC 304.4 - Structural Members   | All structural members shall be maintained free from deterioration and shall be capable of safely supporting the imposed dead and live loads.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | The northeast and southwest corners of the structure are exhibiting signs of settling and are posing a potential hazard for collapse. | *Open |
| 04/20/2023 | IPMC 304.6 - Exterior Walls       | All exterior walls shall be free from holes, breaks, and loose or rotting materials; and maintained weatherproof and properly surface-coated where required to prevent deterioration.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Exterior walls of the structure have breaks, cracks, and loose materials and are not weatherproof or properly surface-coated.         | *Open |
| 05/23/2023 | IPMC 304.7 - Roofs and Drainage   | The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Large hole in the roof over the northwest room that admits rain into the interior of the building.                                    | *Open |
| 05/23/2023 | IPMC 305.1 - General              | The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. Occupants shall keep that part of the structure which they occupy or control in a clean and sanitary condition. Every owner of a structure containing a rooming house, housekeeping units, a hotel, a dormitory, two or more dwelling units or two or more nonresidential occupancies, shall maintain, in a clean and sanitary condition, the shared or public areas of the structure and exterior property.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | The Interior of the building is not in a sanitary condition.                                                                          | *Open |
| 05/23/2023 | IPMC 305.1.1. - Unsafe Conditions | The following conditions shall be determined as unsafe and shall be repaired or replaced to comply with the International Building Code or the International Existing Building Code as required for existing buildings:<br>1. The nominal strength of any structural member is exceeded by nominal loads, the load effects or the required strength.<br>2. The anchorage of the floor or roof to walls or columns, and of walls and columns to foundations is not capable of resisting all nominal loads or load effects.<br>3. Structures or components thereof that have reached their limit state.<br>4. Structural members are incapable of supporting nominal loads and load effects.<br>5. Stairs, landings, balconies and all similar walking surfaces, including guards and handrails, are not structurally sound, not properly anchored or are anchored with connections not capable of supporting all nominal loads and resisting all load effects.<br>6. Foundation systems that are not firmly supported by footings are not plumb and free from open cracks and breaks, are not properly anchored or are not capable of supporting all nominal loads and resisting all load effects. | Sheetrock in the northwest and southwest rooms have fallen from the rafters.                                                          | *Open |
|            |                                   | Exceptions:<br>1. Where substantiated otherwise by an approved method.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                       |       |

2. Demolition of unsafe conditions shall be permitted where approved by the code official.

|            |                                          |                                                                                                                                   |                                                                                               |       |
|------------|------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------|
| 05/23/2023 | IPMC 305.4 - Stairs and Walking Surfaces | Every stair, ramp, landing, balcony, porch, deck or other walking surface shall be maintained in sound condition and good repair. | Carpet in northwest and southwest rooms are not maintained in sound condition or good repair. | *Open |
|------------|------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------|

### Uploaded Files

| Date       | File Name                                                                           |
|------------|-------------------------------------------------------------------------------------|
| 05/24/2023 | <a href="#">15529013-JoshSides-05-23-2023-20-10-17-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529007-JoshSides-05-23-2023-20-11-11-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529008-JoshSides-05-23-2023-20-11-03-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529009-JoshSides-05-23-2023-20-10-53-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529010-JoshSides-05-23-2023-20-10-43-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529011-JoshSides-05-23-2023-20-10-34-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529012-JoshSides-05-23-2023-20-10-24-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529001-JoshSides-05-23-2023-20-09-39-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529003-JoshSides-05-23-2023-20-09-29-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529004-JoshSides-05-23-2023-20-09-22-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529005-JoshSides-05-23-2023-20-09-14-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529006-JoshSides-05-23-2023-20-08-28-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528998-JoshSides-05-23-2023-20-10-00-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528999-JoshSides-05-23-2023-20-09-48-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15529000-JoshSides-05-23-2023-20-09-44-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528937-JoshSides-05-23-2023-20-14-41-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528938-JoshSides-05-23-2023-20-14-32-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528931-JoshSides-05-23-2023-20-12-21-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528932-JoshSides-05-23-2023-20-12-12-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528933-JoshSides-05-23-2023-20-12-05-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528934-JoshSides-05-23-2023-20-11-55-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528935-JoshSides-05-23-2023-20-11-47-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528936-JoshSides-05-23-2023-20-11-19-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528930-JoshSides-05-23-2023-20-12-45-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528826-JoshSides-05-23-2023-20-18-27-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528827-JoshSides-05-23-2023-20-17-10-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528820-JoshSides-05-23-2023-20-28-34-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528821-JoshSides-05-23-2023-20-28-18-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528822-JoshSides-05-23-2023-20-19-26-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528823-JoshSides-05-23-2023-20-19-08-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528824-JoshSides-05-23-2023-20-18-43-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528825-JoshSides-05-23-2023-20-18-33-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528814-JoshSides-05-23-2023-20-15-32-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528815-JoshSides-05-23-2023-20-15-13-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528816-JoshSides-05-23-2023-20-15-03-UTC-308 N White Sands SW.jpg</a> |
| 05/24/2023 | <a href="#">15528817-JoshSides-05-23-2023-20-14-49-UTC-308 N White Sands SW.jpg</a> |

|            |                                                                                            |
|------------|--------------------------------------------------------------------------------------------|
| 05/24/2023 | <a href="#"><u>15528818-JoshSides-05-23-2023-20-28-43-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528819-JoshSides-05-23-2023-20-28-38-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528808-JoshSides-05-23-2023-20-16-45-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528809-JoshSides-05-23-2023-20-16-40-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528810-JoshSides-05-23-2023-20-16-30-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528811-JoshSides-05-23-2023-20-16-23-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528812-JoshSides-05-23-2023-20-16-01-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15528813-JoshSides-05-23-2023-20-15-48-UTC-308 N White Sands SW.jpg</u></a> |
| 05/24/2023 | <a href="#"><u>15527229-FILED Search Warrant 308 N White Sands Blvd.pdf</u></a>            |
| 05/23/2023 | <a href="#"><u>15512899-White Sands N 308 search warrant signed &amp; dated.pdf</u></a>    |
| 05/02/2023 | <a href="#"><u>15226905-N White Sands 308 Certified mail label signed.pdf</u></a>          |
| 04/26/2023 | <a href="#"><u>15176819-North Whitesands 308 IPMC paperwork.pdf</u></a>                    |
| 04/26/2023 | <a href="#"><u>15176793-N. White Sands 308 Certified label pre-mailing.pdf</u></a>         |
| 04/26/2023 | <a href="#"><u>15176794-N. White Sands 308 Certified mail scan IPMC.pdf</u></a>            |
| 04/26/2023 | <a href="#"><u>15166766-JoshSides-04-20-2023-16-02-03-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166760-JoshSides-04-20-2023-16-05-20-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166761-JoshSides-04-20-2023-16-07-06-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166762-JoshSides-04-20-2023-16-07-21-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166763-JoshSides-04-20-2023-16-01-28-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166764-JoshSides-04-20-2023-16-01-42-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166765-JoshSides-04-20-2023-16-01-54-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166754-JoshSides-04-20-2023-16-03-46-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166755-JoshSides-04-20-2023-16-04-01-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166756-JoshSides-04-20-2023-16-04-09-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166757-JoshSides-04-20-2023-16-04-14-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166759-JoshSides-04-20-2023-16-05-09-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166748-JoshSides-04-20-2023-16-02-11-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166749-JoshSides-04-20-2023-16-02-29-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166750-JoshSides-04-20-2023-16-02-40-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166751-JoshSides-04-20-2023-16-03-01-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166752-JoshSides-04-20-2023-16-03-08-UTC-308 N White Sands BL.jpg</u></a> |
| 04/26/2023 | <a href="#"><u>15166753-JoshSides-04-20-2023-16-03-33-UTC-308 N White Sands BL.jpg</u></a> |